







- Pressure Gauge
- Druckanzeige

Druckanzeige



Blech: S Duruhlicht: L

Produkt Nr.	Durchmesser  mm	Arbeitsvoltage  V	Zifferblatt	Anzeigebereich ↔ bar ↔	
11 04 01	60	24	S	0-5	
11 04 12	52	12	S	0-10	
11 04 17	52	12	S	0-7	
11 04 19	60	12	S	0-10	
11 04 20	52	12	S	0-7	
11 04 21	52	24	S	0-5	
11 04 22	52	24	S	0-10	
11 04 23	60	24	S	0-10	
11 04 24	52	24	S	0-7	
11 04 25	52	24	S	0-25	
11 04 27	60	24	S	0-5	
11 04 28	52	24	S	0-7	
11 04 29	52	12	S	0-5	
11 04 30	52	24	L	0-7	
11 04 31	52	24	S	0-7	
11 04 32	52	12	S	0-7	
11 04 33			S	0-5	
11 04 34	52	24	L	0-7	
11 04 35	52	24	S	0-7	
11 04 36	52	24	L	0-7	
11 04 37	52	12	L	0-7	
11 04 38	52	24	L	0-5	
11 04 39	52	24	L	0-7	
11 04 40	52	12	S	0-7	
11 04 43	52	24	S	0-10	
11 04 50	52	12	S	0-10	
11 04 51	60	12	S	0-5	
11 04 52	52	12	S	0-10	
11 04 53	52	24	S	0-10	
11 04 54	52	24	S	0-10	
11 04 57	60	12	S	0-10	
11 04 60	52	12	S	0-10	
11 04 61	52	24	S	0-10	
11 04 62	52	24	S	0-7	
11 04 64	52	24	L	0-5	
11 04 67	52	24	S	0-5	
11 04 68	60	24	S	0-10	Massaefrei
11 04 69	52	24	S	0-10	Massaefrei
11 04 70	52	12	S	0-5	Massaefrei
11 04 71	52	12	S	0-10	
11 04 72	52	24	L	0-3	
11 04 73	60	24	SS	0-10	
11 04 76	60	12	S	0-25	
11 04 80	52	12	S	0-25	