



# Drehzahlmesser



- Tachometer
- Drehzahlmesser

# Drehzahlmesser



Blech: S Duruhlicht: L

Produkt Nr.	Durchmesser  mm	Arbeitsvoltage  V	Anzeigebereich 	Zifferblatt
11 08 08	80	24	0..4000	L
11 08 10	100	24	0..4000	L
11 08 11	100	24	0..4000	L
11 08 12	80	12	0..3500	S
11 08 13	80	12	0..4000	S
11 08 14	80	12	0..4000	S
11 08 15	80	12	0..3500	S
11 08 16	80	24	0..3500	S
11 08 17	100	12	0..2500	S
11 08 19	100	24	0..4000	L
11 08 20	60	12	0..4000	L
11 08 21	80	12	0..4000	S
11 08 24	80	24	0..3500	L
11 08 26	80	12	100..3500	S
11 08 27	100	24	100..3500	S
11 08 31	100	24	0..4000	L
11 08 32	140	24	100..2700	S
11 08 34	103,5	12	0..1400	S
11 08 36	80	24	0..2500	L
11 08 38	100	24	0..4000	L
11 08 39	80	24	0..4000	L
11 08 40	100	24	0..3000	L
11 08 41	80	12	0..3500	S
11 08 42	80	24	0..4000	S
11 08 44	80	12	0..4000	L
11 08 47	80	12	0..3500	L
11 08 48	100	24	0..4000	L
11 08 50	100	24	0..3000	L